

PISTON SKIRTS reconditioning

Piston skirts can be fully reconditioned at Veeanco, our unique service offers aluminium weld repairs back to original manufacturer standards at a fraction of the cost of new!

On receipt at our works, all components are thoroughly cleaned, degreased and identified with a unique reference number to ensure traceability.

A **full inspection report** is produced, including photographs and sent to the customer for approval including recommendations for repair.

The skirt is then machined to remove all existing defects and grooves if oversize in preparation for the **aluminium weld process**.


The **aluminium weld process** is then carried out to the defective areas.

This is followed by precision re-machining of the ring grooves and other welded areas back to original limits and tolerances, carried out in our own state-of-the-art workshops.

The Skirt is then cleaned and complete.



All work carried out on piston skirts is approved by class.



ZACHROME WORKS : SHEFFIELD ROAD : WHITTINGTON MOOR : CHESTERFIELD S41 8NH : TEL. 01246 452 152 : FAX. 01246 455 940 : EMAIL SALES@VEEANCO.COM

